

VEHICLE INSPECTION REPORT

WV23BYK

Iveco S-Way 570

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 17/07/2023

Year 2023

Mileage 284,091 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFS62NW10C496045

Body Style Tractor Unit

MOT Due 31/07/2026

Cab Type AS SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features


- Navigation system
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bumper Front
Scratched
UpTo 25mm Thru Paint

Interior

Carpets Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK